

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0782/1
Work Order Type: Weatherization

Audit Name: 80008KN0782-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0782

Alt. Client ID: Knox

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1950

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0782
Alt. Client ID: Knox

Work Order (Bid Form)

Work Order Name: WO/80008KN0782/1 Report Run On: 5/8/2010 DOE Weatherization Assistant Version 8.6.0 Page 1 of 9

Measures

	Measure	1 Infil	tration Redctn			Componen	ts			Inspected
Comment D1 Open ring. 19 air seals needed. Weatherstrip attic access, I Seal plumbing penetrations. Beaded ceiling and drop ceiling in sources of air leakage. Reduce air infiltration with 19 air seals. is equal to 100 cfms. It is the responsibility of the contractor to leaks. This is best performed with a Blower Door. Contractor m exceed the targeted #. A house must not be brought below 150 pascals. No CHANGE ORDER for air seals below the targeted "Open" Ring, Front Door, 5047 CFM @ 50 pascals. Target is 50 PA					n back as. Each o find the must me fi00 cfm	are majo air seal e air eet or @ 50	r			
						Estimated			Actual	
#	,		Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellan	eous Su	Infiltration Reduction	Each	19	7				
2	Labor		labor	Each	19		7/2			
C	ther Detail									
L							1,111			
							7.17.1			
_					leasur	Sub Total:		s	ub Total:	
	Field Notes	s:								

	Measure 2 D	WH Pipe Insulation			Componen	ts			Inspected
					Estimated	! 		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.			 I L.		J I		
2	Labor	DHW Pipe Insulation	Each	1					
C	ther Detail								
L	· · · · · · · · · · · · · · · · · · ·								
	70.								
				/leasur	e Sub Total:	1774		Sub Total:	
	Fleld Notes:			***************************************			1	L	

Report Run On: 5/8/2010

Measure	3 F	loor Ins. R-19			Componen	its F2			Inspected
Comment	Stand subfid (e.g. comp	ides labor cost. Contractor's e installing insulation. Contradads. Insulation is installed for above (paper side again staves for blankets). Insulations. Refer to Appendictions of the state of the sta	ractor to in I to mainta est subfloc tion to ha	nstall u ain per or) incl ve NO	ising Resnet manent cont uding necess gaps, voids	Grade 1 tact with the sary supp	he orts		
					Estimated			Actual	
# Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	n	Floor Insulation - Fiberglass Batts - R-19	SqFt	270					
2 Labor		Floor Insulation - Fiberglass Batts - R-19	SqFt	270					7
Other Detail	<u> </u>								
			ı	Measur	e Sub Total:			Sub Total:	
Field Note	s:							L	

Meas	ure 4 Flo	or Ins. R-19			Componen	ts F1			Inspected
Comm	Standa subfloc (e.g. st	es labor cost. Contractor's installing insulation. Continutes. Insulation is installed or above (paper side again aves for blankets). Insulations. Refer to Appendicutheast Field Guide.	actor to ir I to mainta st subfloo tion to ha	nstall u ain per or) inclu ve NO	sing Resnet manent cont uding necess gaps, voids,	Grade 1 act with t sary supp or	he orts		
# ##-4-					Estimated	74444		Actual	1764
# Mater	ial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insula	ation	Floor Insulation - Fiberglass Batts - R-19	SqFt	200					770001
2 Laboi	•	Floor Insulation - Fiberglass Batts - R-19	SqFt	200					
Other Do				Measure	Sub Total:		S	Sub Total:	
	****		TT		7/18		-		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

measure 5 Attic Ins. R-38				Components A1					Inspected	
*Includes labor cost. Contractor to in attic space showing depth of insulat access. Install baffles as needed to soffit and covering vent. Seal all ho insulating. Seal around chimney wire silicone or fire resistant foam. Instat access and weather strip with foam Grade 1 Standards. Refer to Appendaterials and Southeast Field Guide				uild insont loose ps, and t meta fibergi	ulation dam if fill insulation if penetration if and high teleass batt sec	around a on from e ons in attice emperatu oured to a	ettic ntering before re attic	ı		
,,,	•• • • • • •				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	Attic Insulation - Blown Fiberglass - R-38	SqFt	1244						
2	Labor	Attic Insulation - Blown Fiberglass - R-38	SqFt	1244						
C	Other Detall									
Ĺ										
						700				
_		_	I	Measure	Sub Total:		s	ub Total:		
	Field Notes:			T) Pha		704	****			

i	Measure 6 DWH Tank Insulation Comment extend pressure relief pipe as needed				Components					
C					•				Inspected	
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Hot Water Equipm	DHW Tank Insulation	Each	1						
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.					L			
2	Labor	DHW Tank Insulation	Each	1						
0	ther Detail						72	~J	<u>,,,,</u>]	
][
] [
				Measure	Sub Total:		 S	ub Total:		
	Field Notes:				<u> </u>		···	L		

<i>Measure</i> 7 Fix ver	Ventilation Inadequate	e (Attic) (2	low	Componen	its			Inspected
change	ents installed on High pa 0 of the area of space b as allowed. Refer to Atta als and Southeast Field	eing ventila chment A- :	ated 1	2 high and 1	12 low N	^	1	
NOTE:	Do not install roof vents	on front pa	rt of h	ouse.				
			-	Estimated	•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety 	Roof Vents	Each	2					
	Location				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	L	J	
2 Labor	Labor	Each	2					
Other Detail						L		
			<u> </u>				1	
			L					
Field Notes:			Measur	e Sub Total:		Sı	ıb Total:	
Comment Must be walls an earth. M	or Barrier Needed (200 6 mil poly. Must be insta d support piers. Must be ust be secured at all sea ization Materials and So	alled 100% e securely f ams. Refer	of crav astend	ed. Must be c schment A- S	6" turned	nun ta		Inspected
# Material / Labor	*	-	·	Estimated			Actual	
	Description / Comment	Units	Qty	Unit Cost	Total	Qty L	Init Cost	Total
Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	200					
2 Labor	Labor	SqFt	200					
Other Detail			i					
					[
Fleid Notes:		M	easure	Sub Total:		Sub	Total:	
i idia iyotes;								7

Client Name:

Client ID: 80008KN0782 Alt. Client ID: Knox Work Order (Bid Form)
Work Order Name: WO/80008KN0782/1
Report Run On: 5/8/2010

DOE Weatherization Assistant Version 8.6.0

Page 8 of 9

Work Order Grand Total:	Grand Total: